

# XSOLUTION KIT

Abrasive pads, C1.CREAM, F5.12, X.POLISH, gloves, paper cloth

## MATERIALS

- Marble
- Granite
- Natural stone

## APPLICATION FIELDS

- Coverings
- Kitchen Countertops
- Bathroom Countertops
- Tables



## CHARACTERISTICS

- Abrasive pads with different grits
- C1.CREAM removes dry residues and encrustations superficial
- F5.12 liquid wax with polishing power
- X. POLISH polishing powder
- Restores damaged, corroded, opacified surfaces with few steps, easy accessories and few products avoiding thus the smoothing and polishing traditional

## PACKAGING

- Composed kit of accessories and bottles of 0,2 Lt/Kg

## WARNINGS

Apply at an ambient temperature between 10°C - 20°C. Keep out of reach of children. Do not disperse into the environment. Before use, consult the safety data sheet and label, in which risks and safety are highlighted for the correct use of personal protective equipment. All information contained in this page is based on information we believe to be reliable; however, not knowing the conditions of the materials treated and the way you use the product, ITALIAN XS declines all responsibility about The suitability of the material for each particular application. Store the product in the original containers and hermetically closed. Store the product at a temperature between 5° C - 20° C. If stored as indicated above, the product has a shelf life of 12 months. It is advisable to carry out preventive tests on small areas as our responsibility is limited at the cost of the product. No liability for damage caused by negligence or misuse of the product.

## INSTRUCTION

### SMOOTHED SURFACES

Take the BLACK TRIANGLE, pour very few water on corrosion and make circular moviments for around a minute. You noted that during this moviments on corrosion the water changed colour becomed white. This mean that the work with black triangle is correct. Now you rinse and dry all. Look in backlight if there are yet visible marks of corrosion. If yes, repeat this step with BLACK TRIANGLE until to complete the elimination of corrosion. Remember you to rinse and dry all. At the end you could note some small marks or opacifications. In this case use the product called C1.CREAM. Pour it and rub with WHITE SQUARE PAD for around a minute until to uniform the area that you smoothed.

### POLISHED SURFACES

Make all steps indicated for smoothed surfaces. With the successive triangles increases the work area. Remember you that the triangles work with very few water. With the BROWN TRIANGLE make circular moviments for around a minute. You rinse and dry all. Take the GREEN TRIANGLE and make circular moviments for around a minute. You rinse and dry all. Take the YELLOW TRIANGLE and make circular moviments for around a minute. You rinse and dry all. The surface that have restore isn't yet polish and uniform as the rest of the surface. It is arrive the moment to use powder called X.POLISH. Pour it few on work area. Add a drop of water and with clean WHITE SQUARE PAD rub doing pression. If you want have a perfect polishing as a mirror apply on all surface the product called F5.12 with microfibre cloth. Wait that dry and after with wool cloth rub well the surface.